

FIG.5




FIG.6




FIG.7




FIG.8




FIG.9




FIG. 10




FIG.11

FIG. 12







FIG.13B







70b

## SEWING MACHINE CONTROL PROGRAM

- SEWING PROGRAM
- CASSETTE ATTACHMENT/ DETACHMENT CONTROL PROGRAM
- NEEDLE BAR POSITION CONTROL PROGRAM
- DISPLAY CONTROL PROGRAM

FIG.16




FIG. 17





FIG. 18

		SPINDLE ANGI	SPINDLE ANGLE IN OPERATIONOF NEEDLE UP-DOWN KEY	NOF NEEDLE U	IP-DOWN KEY
	/.	UPPER STOP POSITION	UPPER STOP POSITION LOWER STOP POSITION	LOWER STOP POSITION	LOWER STOP POSITION VPPER STOP POSITION
	ATTACHED	LOWER STOP POSITION	LOWER STOP POSITION	UPPER STOP POSITION	UPPER STOP POSITION
IN OPERATION OF NEEDLE UP-DOWN KEY	UNATTACHED	(LOWER STOP )  UPPER STOP POSITION	(LOWER STOP ) UPPER STOP POSITION	UPPER STOP POSITION	UPPER STOP POSITION

FIG. 19






FIG.21